EXHIBIT C

Sumr	nary of Claim - Delphi	CDN\$	USD\$
1	Excess and Obsolete material		\$645,236.00
2	Tooling, NRE, and Prototyping Charges	\$503,594.80	\$403,983.75
3	Material consumed in Prototyping	\$1,625.90	\$77,710.77 \$1,304.30
4 .	Consulting Services	\$47,302.00	\$39,076.56 \$37,945.66
5	Leased Equipment	\$4,450.00	\$3,569.79
6	CLS Labour charges for Delphi - Matchbox		\$532,418.56
7	Outstanding Invoices - Not included above		\$58,381.00 \$1,799,626.39

Note: Exchange Rate CDN/USD

0.8022

Filed 11/22/06 Entered 11/22/06 15:22:02

	05-44481-rdd	Doc 5744-3	Filed 11	/22/06	Entered 11/22/06	15:22:02	Ex	hibit C	
Item No	Item Dscrpn		Cmdty Dscrpn	Pastomer Fall	No Vendor Std Name	Std Cost L/T	WEEKS		EXTENDED \$ 645,236
DST001794	MATCHBOX CABLE OVE	RMOULD ASSEMBLY-CAB	CABLE	DST001794	TYCO	4.60	9	19600	
DST001702DFS	Low power FM stereo IC, 0		LINEAR	DST001702	PHILIPS SEMICONDUCTOR	2.25	17	35386	
DST001700DFS		FN48-MICRO CONTROLLE		DST001700	FREESCALE SEMICONDUC		18	37900	
DST002004DFS	P-Channel 30V 7A MOSFE		TRANSISTOR		ON SEMICONDUCTOR	0.31	12		
DST001704DFS	PWM controller, TSSOP16		LINEAR	DST001704	TEXAS INSTRUMENTS	0.69	15	45700	
DST001805DFS	Headphone-ELECTRO ME	ECH SUB ASM	ELECTRO ME		DAESUNG ELECTRIC	16.94	13	1780	
DST001727DFS		IAGEMENT IC WITH FETS,		DST001727	TEXAS INSTRUMENTS	1.43	24	18500	
DST001865DFS	CAP, POSCAP, 20%, 100		CAPACITOR		PANASONIC	0.85	10	29800	
DST001734DFS	XTAL, 13MHZ, SMT, 13PF		FREQ CONTR		RALTRON ELECTRONICS	0.43	15	53000	
DST001764DFS	Single-supply Dual Op-Am	p, VSSOP-8-LINEA	LINEAR	DST001764	TEXAS INSTRUMENTS	0.63	22	35000	
DST001731DFS	Right-angle SMB PCB jack	k-CONNECTOR RECEP	CONNECTOR	DST001731	AMPHENOL	0.79	9	27360	
DST001838DFS	P-Channel 20V MOSFET-	TRANSISTOR FET P-CH	TRANSISTOR	DST001838	VISHAY	0.4	9	37500	
DST001726DFS	CAP, 1812, 10%, X7R, 47		CAPACITOR	DST001726	TDK	0.36	12	37000	
DST001857DFS	4-POSITION JOYSTICK S	SWITCH-SWITCH MECH -	SWITCH	DST001857	C & K COMPONENTS	0.38	9	32000	\$ 12,160
DST001897DFS	30-pin vertical FPC connec		CONNECTOR		MOLEX	0.35	10	28700	\$ 10,045
DST001899DFS		STIC, TOP-PACKAGING BL			STEPHEN GOULD	0.40	4	23000	\$ 9,200
DST001706DFS	Low-voltage variable capa	•	DIODE-RECT		PHILIPS SEMICONDUCTOR	0.15	9	54000	\$ 8,280
DST001864DFS	CAP, 1210, 20%, X7R, 220		CAPACITOR		KEMET ELECTRONICS	0.23	11	36000	
DST002000DFS		STIC, BOTTOM-PACKAGIN	PACKAGING	DST002000	STEPHEN GOULD	0.40	4	20010	\$ 8,004
DST001741DFS	4MHZ CRYSTAL RESONA		FREQ CONTR		AVX	0.26	18	30000	\$ 7,920
DST001771DFS	CAP,0603,10%,X5R,0.1uF		CAPACITOR	DST001771	AVX	0.006	10	1105400	\$ 6,632
DST002001DFS	INSERT, PACKAGING-PA		PACKAGING		STEPHEN GOULD	0.30	4	20200	\$ 5,959
DST002006DFS		BATTERY CONNECTOR V		DST002006	SUYIN CONNECTOR	0.55	7	10800	\$ 5,940
DST001867DFS	2W stereo amp with volum		LOGIC	DST001867	TEXAS INSTRUMENTS	1.25	17	4000	\$ 5,000
DST001705DFS	Dual 250mW audio PA with		LINEAR	DST001705	NATIONAL SEMICONDUCTO	F 0.27	13	17500	\$ 4,725
DST001753DFS			PLASTIC PART		CUSTOM PLASTICS	2.17	10	2124	\$ 4,605
DST001827DFS	Trench power MOSFET, 3		TRANSISTOR		ON SEMICONDUCTOR	0.07	7	61149	\$ 4,464
DST001770DFS	CAP, 10 uF tantalum, 10V,		CAPACITOR		AVX	0.033	10	120000	\$ 3,960
DST001768DFS	220uF tantalum, 6.3V, case				AVX	0.153	10	25200	\$ 3,856
DST002033DFS	Picture of Roady-PACKAG		PACKAGING		STEPHEN GOULD	0.07	4	53000	
DST001708DFS	COIL IND, 33nH, 2%, 0603		INDUCTOR	DST001708	COILCRAFT	0.053	9	60000	
DST001806DFS	AC/DC Power Adapter Brid		POWER SUPF		HON-KWANG ELECTRIC	1.95	7	1591	
DST001862DFS DST001891DFS	INDUCTOR, SMT, 10UH,		INDUCTOR	DST001862	SUMIDA	0.26	10	11250	
	M1.6x4 self-tapping screw,	· ·	SCREW	DST001891	IRWIN INDUSTRIAL	0.03	13	106000	
DST001823DFS DST001787DFS	5-pin right-angle header, P		CONNECTOR		MOLEX	0.13	3	21000	. ,
DST001787DFS	RES, 0402, 5%, 10 OHMS		RESISTOR	DST001787	KOA SPEER ELECTRONICS	0.01	7	229715	
DST001890DFS	3A 40V Schottky rectifier-D		DIODE-RECT		ON SEMICONDUCTOR	0.08	19.2	28700	
DST001090DFS	1-32 * 4MM 6-LOBE (6) PA		SCREW	DST001890	QUALITY SCREW & NUT	0.03	21	82165	
DST002007DFS	Right-angle header-CONN		CONNECTOR		MOLEX	0.04	6	53000	
DST001032DFS	200mA adjustable LDO, SC		LINEAR	DST001892	TEXAS INSTRUMENTS	0.25	5	8060	
DST002013DFS	5-pos 0.100 ribbon cable-C CAP,CER, 0.47UF, 10V, 10		CABLE	DST002015	MOLEX	0.04	6	45000	
DST001831DFS	0603 ESD CAPACITOR-C		CAPACITOR		KEMET ELECTRONICS	0.0095	11	198850	
DST001854DFS	Triple common-mode chok		CAPACITOR INDUCTOR	DST001829	BUSSMANN	0.03	12	65000	
DST002029DFS	EMI shield clips-CLIP MET		CLIP	DST001854 DST002029	MURATA ELECTRONICS	0.24	9	7600	
DST002031DFS	BAR CODE CARD-PACKA		PACKAGING		AUTOSPLICE DUMMY VENDOR	0.07 0.07	2 17	24100 : 22693 :	
DST002009DFS	Single 2-input positive AND		LOGIC	DST002009	TEXAS INSTRUMENTS	0.035	8	40000	
DST001732DFS	3.5mm miniature audio jaci		CONNECTOR		DIGI-KEY	0.19	7	7450	
DST001783DFS	CAP, 0402, 10%, X7R, 22r		CAPACITOR		AVX	0.0035	14	376000	
DST001896DFS	30V Schottky Diode, SOT2		DIODE-RECT		ON SEMICONDUCTOR	0.034	9	38398	
DST002008DFS	CAPC, X5R, 16V, 10uF, 10		CAPACITOR		AVX	0.043	11	19020	
30000PK1840DFS	Corrugated overpack sleev		PACKAGING	30000PK1840	BIRD PACKAGING	6.83	2	100	
DST001740DFS	Single inverter, 3.3V CMOS		LOGIC	DST001740	TEXAS INSTRUMENTS	0.03	9	18000	
DST001858DFS	General purpose NPN trans		TRANSISTOR		ON SEMICONDUCTOR	0.0094	9	55650	
DST001788DFS	RES, 0402, 5%, 0-OHM JU		RESISTOR	DST001788	KOA SPEER ELECTRONICS	0.00065	7	789500	
DST001822DFS	RES, 0402, 5%, 20K OHM		RESISTOR	DST001822	KOA SPEER ELECTRONICS	0.0003	7	37800	
DST002017DFS	RF ID Security Tag-LABEL		LABEL	DST002017	WS PACKAGING GROUP	0.045	2	7500	
DST001785DFS	CAP, 0402, 10%, NPO, 27			DST001785	KEMET ELECTRONICS	0.002	11	142000	
DST001835DFS	FERRITE BEAD, 0805, 600		INDUCTOR	DST001835	MURATA ELECTRONICS	0.0112	7	23950	
DST001782DFS	CAP, 0402, 10%, X7R, 10n			DST001782	AVX	0.0016	10	164700	
DST001790DFS	RES, 0402, 5%, 33K OHMS		RESISTOR	DST001790	KOA SPEER ELECTRONICS	0.00065	7	322100	
DST001777DFS	CAP, 0402, 10%, X7R, 33n			DST001777	AVX	0.0035	10	55000	
DST001791DFS	RES, 0402, 5%, 100K OHM		RESISTOR	DST001791	KOA SPEER ELECTRONICS	0.00065	7	289600	
DST001810DFS	CAP, 0603, 10%, X7R or X			DST001810	AVX	0.0055	10	32000	
DST001720DFS	CAP, 0603, 10%, X7R, 47n			DST001720	KEMET ELECTRONICS	0.0065	11	15324	
DST001869DFS	CAP 10UF, 20.0%, 25.0V, 2			DST001869	TAIYO YUDEN	0.085	6	1000	



/	Î
(<u>へ</u>

		o armen de	g rytherens a		e magaza kanan kanan kana	Terresta settenas, ma	e emission are presented a		N
4500347986				07/27/2004		0.000	07/30/2004	Initial Tooling Dies Issued by POD Group	\$11,950.00
4500347986		00020	23439	07/27/2004	1.000	0.000	07/30/2004	Initial Tooling Dies Issued by POD Group	\$9,700.00
4500347986			23439	07/27/2004		0.000	07/30/2004	Initial Tooling Dies Issued by POD Group	\$7,700.00
4500347986 4500347986			23439	07/27/2004	1.000			Initial Tooling Dies Issued by POD Group	\$13,950.00
4500347986			23439	07/27/2004				Initial Tooling Dies Issued by POD Group Initial Tooling Dies Issued by POD Group	\$11,900.00
4500347986			23439	07/27/2004				Initial Tooling Dies Issued by POD Group	\$7,450.00 \$6,450.00
4500347986			23439	07/27/2004		0.000	07/30/2004	Initial Tooling Dies Issued by POD Group	\$4,950.00
4500347986			23439	07/27/2004	1.000	0.000	07/30/2004	Initial Tooling Dies Issued by POD Group	\$9,800.00
4500347986	то	00110	23439	07/27/2004	1.000	0.000	07/30/2004	Initial Tooling Dies Issued by POD Group	\$5,950.00
i	l	ı	ł	ł	1	1		8/6 PO placed for Delphi POD, preliminary	1
4500353876	TEST ENG/PARTS	100010	23430	08/06/2004	40,000	۰	00/05/2004	pricing received from Adrian Dizon ding	*075.00
	TEST ENG/PARTS			08/06/2004			08/25/2004	ditto	\$975.00 \$975.00
	TEST ENG/PARTS		23439	08/06/2004					\$975.00
	TEST ENG/PARTS			08/06/2004					\$975.00
4500353876				08/06/2004		0.000	08/25/2004		\$975.00
4500353876	TEST ENG/PARTS	100060	23439	08/06/2004	80.000	0.000			\$1,950.00
4500353876	TEST ENG/PARTS TEST ENG/PARTS			08/06/2004	40.000	0.000			\$975.00 \$975.00
	TEST ENG/PARTS		23439	08/06/2004	40.000	0.000			\$975.00
4500353876	TEST ENG/PARTS	00100	23439	08/06/2004	40.000		08/25/2004		\$975.00
	TEST ENG/PARTS			08/06/2004	40.000				\$975.00
4500369946		00010		09/08/2004	1.000			Initial Tooling Dies Issued by POD Group	\$21,880.00
4500369946 4500369946		00030		09/08/2004	1.000	0.000		Initial Tooling Dies Issued by POD Group Initial Tooling Dies Issued by POD Group	\$22,720.00 \$19,400.00
4500369946		00040		09/08/2004	1.000			Initial Tooling Dies Issued by POD Group	\$16,920.00
4500369946	TO	00050	23439	09/08/2004	1.000			Initial Tooling Dies Issued by POD Group	\$17,280.00
4500369946		00060		09/08/2004	1.000	0.000	07/30/2004	Initial Tooling Dies Issued by POD Group	\$10,680.00
4500369946		00070		09/08/2004	1.000			Initial Tooling Dies Issued by POD Group	\$6,560.00
4500369946 4500369946			23439 23439	09/08/2004	1.000			Initial Tooling Dies Issued by POD Group	\$5,120.00
4500369946			23439	09/08/2004	1.000			Initial Tooling Dies Issued by POD Group Initial Tooling Dies Issued by POD Group	\$13,100.00
4500369947			23439	09/08/2004	1.000			Initial Tooling Dies Issued by POD Group	\$5,000.00 \$5,470.00
4500369947			23439	09/08/2004	1.000			Initial Tooling Dies Issued by POD Group	\$5,680.00
4500369947			23439	09/08/2004	1.000			Initial Tooling Dies Issued by POD Group	\$4,850.00
4500369947			23439	09/08/2004	1.000			Initial Tooling Dies Issued by POD Group	\$4,230.00
4500369947 4500369947			23439	09/08/2004	1.000	0.000		Initial Tooling Dies Issued by POD Group	\$4,320.00
4500369947			23439 23439	09/08/2004	1.000	0.000		Initial Tooling Dies Issued by POD Group Initial Tooling Dies Issued by POD Group	\$2,670.00 \$1,640.00
4500369947			23439	09/08/2004	1.000	0.000	07/30/2004	Initial Tooling Dies Issued by POD Group	\$1,280.00
	TO	00100	23439	09/08/2004	1.000	0.000	07/30/2004	Initial Tooling Dies Issued by POD Group	\$3,275.00
4500369947	TO	00110	23439	09/08/2004	1.000	0.000		Initial Tooling Dies Issued by POD Group	\$1,250.00
1		1	ĺ	·				9/10 PO PLACED FOR DELPHI MATCHBOX	
1		}	l	1				POD TOOLING OF PLASTICS, THIS PO IS FOR THE DIFFERENCE DUE TO	
4500371124	то	00010	23439	09/10/2004	1.000	0.000	09/10/2004	CHANGES DNG	\$83,525.00
						5.555	Jan 14 200 1	PO created as per the email from Susan Li	₹ 00,0±0.00
1			l					dated 9/13. PO created to order 8 SLA	ĺ
		1	ļ					models along with 2 SLS models. Leadtime is	
1								approx. 5-7 days upon the receipt of the PO.	1
1								Lee Cattell at Customs Plastics to advise best	
4500372908	TEST ENG/PARTS	00010	23439	09/14/2004	12.000	0.000	09/21/2004	ship date for the parts below as the total cost for the 2 parts is \$3,500/gs	\$4,200.00
	TEST ENG/PARTS			09/14/2004	4.000		09/21/2004		\$1,400.00
								This is PO for premium for expediting	V.1.33.33
1								delivery of resin at \$3.00/lb (premium price of	
								\$5.78 less standard price of \$2.78) for 4400	
4500374732	P0020	00010	23439	09/17/2004	1.000	0.000	00/47/0004	lbs required for initial units of Delphi Matchbox Roady unit	642 200 00
4500375412		00010		09/20/2004	1.000			Die cut for LCD lens	\$13,200.00 \$500.00
				56-24-45	1.000	0.000	OGEGEGG	SIG SOL TO COS TOTO	4000.00
1 1								This is a tooling PO for the additional charges	
								\$13,600 to be paid 50% + 40% + 10%	
4500270720	TO	00010	22422	00/20/202			00/00/000	Program: Delphi Matchbox	4
4500379730 4500379730			23439 23439	09/28/2004	1.000		09/28/2004	ditto	\$6,800.00 \$5,440.00
4500379730		00030		09/28/2004	1.000		09/28/2004		\$1,360.00
					1.000	3.000		This is PO for premium for expediting	ψτ,υισ.συ
						ļ		delivery of resin at \$3.00/lb (premium price of	:
								\$5.78 less standard price of \$2.78) for 4400	
1 1								lbs required for initial units of Delphi	
4500380475	P0020	00010	23439	09/29/2004	1.000	0.000	10/01/2004	Matchbox Roady unit – C6600BK1662 Resin AND Colour Matching	\$13,200.00
4500380475			23439	09/29/2004	1.000		10/01/2004		\$13,200.00
4500383140	DST001757DFS		23439	10/06/2004	25,000.000			Production Order	Production Order
4500383140	DST001758DFS	00020	23439	10/06/2004	24,615.000	24,615.000	12/31/2004	Production Order	Production Order
4500383140	DST001855DFS		23439	10/06/2004	25,000.000	25,000.000	10/15/2004	Production Order	Production Order
	DST001750DFS DST001751DFS		23439 23439	10/06/2004	25,000.000			Production Order	Production Order Production Order
	D\$1001751DF\$	00060	23439	10/06/2004	24,357.000 50,000.000			Production Order Production Order	Production Order Production Order
	DST001752DFS	00070	23439	10/06/2004	24,973.000			Production Order	Production Order
4500383144	DST001754DFS	00010	23439	10/06/2004	25,000.000	25,000.000	12/06/2004	Production Order	Production Order
	DST001753DFS		23439	10/06/2004	25,000.000			Production Order	Production Order
	DST001856DFS		23439	10/06/2004	25,000.000	25,000.000	11/15/2004	Production Order	Production Order
4500380207	DST001894DFS DST001754DFS	00040	23439	10/06/2004	16,760.000 29,467.000	20.467.000	12/31/2004	Production Order Production Order	Production Order Production Order
	DST001753DFS	00020		10/18/2004	33,961.000			Production Order	Production Order
4500389207	DST001856DFS	00030	23439	10/18/2004	38,000.000	38,000.000	02/04/2005	Production Order	Production Order
4500389208	DST001757DFS	00010	23439	10/18/2004	39,280.000	39,280.000	12/31/2004	Production Order	Production Order
	DST001758DFS	00020		10/18/2004	31,800,000	31,800.000	12/31/2004	Production Order	Production Order
	DST001855DFS		23439	10/18/2004	38,000.000			Production Order	Production Order
	DST001750DFS DST001751DFS	00040	23439	10/18/2004	39,363.000 38,000.000			Production Order Production Order	Production Order Production Order
	D\$T001756DFS	00060		10/18/2004	52,019.000			Production Order	Production Order
				10/18/2004	28,392.000	28,392.000	01/06/2005	Production Order	Production Order

			1					NRE Charge for Pad printing Chassis and	
<u> </u>		1						PCB Cover:	
1 1								Chassis:	1
1 1								Pre-hardened steel pad printing plate: \$	1
		1						420.00 US funds Holding Fixture: \$ 450.00 US funds	1
1 1		1		1				Black Ink: \$ 125.00 US funds	
1 1		1						Silicone Pad: \$ 50.00 US funds	1
1 1								J	
1 1								PCB Cover:	
1 1		1		1				Pre-hardened steel pad printing plate: \$	
1 1		1						420.00 US funds	}
1 1								Holding Fixture: \$ 400.00 US funds	1
								Col Gray 8c Ink: \$ 150.00 US funds	¢2.055.00
4500398453	N0010	00010	23439	11/08/2004	1.000	0.000	11/08/2004	Sificone Pad: \$ 50.00 US funds	\$2,065.00
}		1		l i		1		Summary of Tool Changes for Metallic Resin:	
1 1		1		l i				Summary or root onanges for inclusive ricons.	1
i i		1	l					i) Lock Roady - add flow restrictor - \$	
1								1,100.00 US funds	
]						ii) Selector Switch - gate changes - \$	
								1,300.00 US funds	
1		1 :						iii) Roady Tray - move gate location - \$	1
1		1						4,500.00 US funds	
l i		1						These charges are necessary to ready the	
4500404705	70	00010	23439	11/19/2004	1.000	0.000	11/19/2004	tools for metallic resin.	\$1,100.00
4500404705				11/19/2004	1.000		11/19/2004		\$1,300.00
4500404705			23439	11/19/2004	1.000		11/19/2004		\$4,500.00
	<u> </u>	1			1.500	0.000			
1			1					4 Way Actuator Switch DST001758: \$	
		1	'					1,200.00 US funds	1
								Selector Switch DST001757: \$ 1,200.00 US	1
		1						funds Lock Roady Tray DST001756: \$ 3,000.00	
		i							
		1	f !					US funds (slight increase - tooling at 2 locations).	1
1		1						Roady Tray DST001752: \$ 4,400.00 US	
1		ł						funds (slight increase - tooling at 2 locations	
1		I						and multiple masking requirement changes).	
		į	1					Chassis DST001753: \$ 4,400.00 US funds	
1		} .						(stight increase - tooling at 2 locations and	i
4500404717	то	00010	23439	11/19/2004	1.000	0.000	11/19/2004	multiple masking requirement changes)	\$1,200.00
4500404717	TO		23439	11/19/2004	1.000		11/19/2004		\$1,200.00
4500404717			23439	11/19/2004	1.000		11/19/2004		\$1,500.00
4500404717			23439	11/19/2004	1.000		11/19/2004		\$4,400.00 \$2,600.00
4500404717	10	00050	23439	11/19/2004	1.000	0.000	11/19/2004	Tooling charge to modify the chassis for flow	\$2,000.00
4500409577	TO	00010	23439	11/26/2004	1.000	0.000	11/26/2004	line problems	\$900.00
4500415584			23439	12/08/2004	1.000	0.000	12/08/2004	Tooling charge for reworking lock latch	\$3,700.00
4500417812	DST001750DFS	00010			25,550.000			Production Order	Production Order
4500417812	DST001750DFS DST001751DFS	00020	23439 23439	12/13/2004 12/13/2004	25,550.000 25,000.000	25,550.000 25,000.000	01/31/2005 01/31/2005	Production Order Production Order	Production Order Production Order
4500417812 4500417812	DST001751DFS DST001754DFS	00020 00030	23439 23439 23439	12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000	25,550.000 25,000.000 33,624.000	01/31/2005 01/31/2005 01/31/2005	Production Order Production Order Production Order	Production Order Production Order Production Order
4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS	00020 00030 00040	23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000	25,550.000 25,000.000 33,624.000 26,500.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005	Production Order Production Order Production Order Production Order	Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001856DFS	00020 00030 00040 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order Production Order Production Order Production Order Production Order Production Order	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS	00020 00030 00040 00050	23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order Production Order Production Order Production Order	Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001856DFS	00020 00030 00040 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order CPI quote Approved by CLS Comments	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001856DFS	00020 00030 00040 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001856DFS	00020 00030 00040 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order CPI quote Approved by CLS. Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001856DFS	00020 00030 00040 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove 4500 charge as CPI is responsible for sink marks (did not mention during DFM).	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001856DFS	00020 00030 00040 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Roady Tray 6,200 7 Please remove cost of	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001856DFS	00020 00030 00040 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Roady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001856DFS	00020 00030 00040 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Roady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection.	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001856DFS	00020 00030 00040 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order CPI quote Approved by CLS. Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Roady Tray &200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001856DFS	00020 00030 00040 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Floady Tray 6,200 7 Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001856DFS	00020 00030 00040 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order CPI quote Approved by CLS. Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Roady Tray &200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001856DFS	00020 00030 00040 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove 4500 charge as CPI is responsible for sink marks (did not mention during DFM). Roady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove 83900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$\$500 charge as CPI is responsible	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001856DFS	00020 00030 00040 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order CPI quote Approved by CLS. Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marts (did not mention during DFM). Roady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsibile for sink marks (did not mention during DFM).	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001856DFS	00020 00030 00040 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Roady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Roads (did not mention during DFM). Cover Roads (did not mention during DFM).	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001856DFS	00020 00030 00040 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	25,550.000 25,000.000 33,624.000 26,500.000 26,850.000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove 45500 charge as CPI is responsible for sink marks (did not mention during DFM). Roady Tray 6,200 7 Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove 23900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove 48500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Roady Tray 7,800 7,800 Cover Roady Tray 7,800 7,800 Cover Roady Tray 7,800 7,800	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS	00020 00030 00040 00050 00050	23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 02/24/2005	25,550,000 25,000,000 33,624,000 26,5500,000 3,240,000	25,550,000 25,000,000 33,624,000 26,500,000 3,240,000 3,240,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Floady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Abasis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Abasis 15,000 3,500 Cap, PCB Cover 3,500 3,500 Cap, PCB Cover 3,500 3,500 Actuator, Selector Switch 350 350	Production Order Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS	00020 00030 00040 00050 00050	23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 02/24/2005	25,550,000 25,000,000 33,624,000 26,5500,000 3,240,000	25,550,000 25,000,000 33,624,000 26,500,000 3,240,000 3,240,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Roady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$9500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Poady Tray 7,800 7,800 Cap, PCB Cover 3,500 3,500 Actuator, Selector Switch 350 350 TOTAL \$73,250 \$49,150	Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST0011754DFS DST0011855DFS DST0011750DFS DST001750DFS	00020 00030 00040 00050 00060	23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 02/24/2005	25.550.000 25.000.000 33.624.000 26.500.000 3.240.000 3.240.000	25,550,000 25,000,000 33,624,000 26,500,000 3,240,000 3,240,000	01/31/2006 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Floady Tray 6,200 7 Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$9500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Poady Tray 7,800 7,800 Cap, PCB Cover 3,500 3,500 Actuator, Selector Switch 350 350 TOTAL \$73,250 \$49,150 Old Chassis Stock as advised 11/5/04 - \$ 4,329 80 US funds.	Production Order Production Order Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST0011754DFS DST0011855DFS DST0011750DFS DST001750DFS	00020 00030 00040 00050 00060	23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 02/24/2005	25,550,000 25,000,000 33,624,000 26,5500,000 3,240,000	25,550,000 25,000,000 33,624,000 26,500,000 3,240,000 3,240,000	01/31/2006 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Roady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$9500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Poady Tray 7,800 7,800 Cap, PCB Cover 3,500 3,500 Actuator, Selector Switch 350 350 TOTAL \$73,250 \$49,150	Production Order Production Order Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500417812	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS TO R0090	000010 000010 000010	23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 02/24/2005	25,550,000 25,000,000 33,624,000 26,550,000 3,240,000 3,240,000 1,000 1,000	25,550,000 25,000,000 33,624,000 26,500,000 3,240,000 3,240,000 0,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marts (did not mention during DFM). PCB Cover 13,200 9,300 Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Roady Tray 7,800 7,800 Cap, PCB Cover 3,500 3,500 Actuator, Selector Switch 350 350 TOTAL \$73,250 \$49,150 Old Chassis Stock as activised 11/5/04 - \$ 4,329.80 US funds. Cancellation Charge for Silver grey locks and switches and paint.	Production Order Production Order Production Order Production Order Production Order Production Order Production Order \$49,150.00
4500417812 4500417812 4500417812 4500417812 4500417812 4500417812 4500420896 4500420896	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS TO R0090 CAA R0110	00010 000010 000010 00010	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 02/24/2006	25,550,000 25,000,000 33,624,000 26,550,000 3,240,000 3,240,000 1,000 1,000 1,000	25,550,000 25,000,000 33,624,000 26,550,000 3,240,000 3,240,000 0,000 0,000 0,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005 02/25/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Floady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$9500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Poady Tray 7,800 7,800 Cap, PCB Cover 3,500 3,500 Actuator, Selector Switch 350 350 TOTAL \$73,250 \$49,150 Old Chassis Stock as advised 11/5/04 - \$ 4,329 80 US funds. Cancellation Charge for Silver grey tocks and switches and paint.	Production Order \$49,150.00 \$44,329.80
4500417812 4500417812 4500417812 4500417812 4500417812 4500420802 4500420809 4500420809 4500420809	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS	00010 000010 00010 00010 00010	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004	25,550,000 25,000,000 33,624,000 26,500,000 3,240,000 3,240,000 1,000 1,000 42,620,000	25,550,000 25,000,000 33,624,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marts (did not mention during DFM). Roady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$9500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Roady Tray 7,800 7,800 Coap. PCB Cover 3,500 3,500 Actuator, Selector Switch 350 350 TOTAL \$73,250 \$49,150 Old Chassis Stock as advised 11/5/04 - \$4,329 80 US funds. Cancellation Charge for Silver grey locks and switches and paint. Chassis Engraving Reduction	Production Order \$49,150.00 \$4,329.80 \$1,200.00 Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500417812 4500420602 4500420602 4500420896 4500420900 4500420817	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS	00020 00030 00040 00060 00060 00010 00010 00010 00010 00010	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 02/24/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004	25,550,000 25,000,000 33,624,000 26,550,000 3,240,000 3,240,000 1,000 1,000 42,620,000 42,620,000 42,220,000	25,550,000 25,000,000 33,624,000 26,550,000 26,850,000 3,240,000 0,000 0,000 40,417,000 42,220,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 02/28/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Roady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$9500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Roady Tray 7,800 7,800 Cap. PCB Cover 3,500 3,500 Actuator, Selector Switch 350 350 TOTAL \$73,250 \$49,150 Old Chassis Stock as advised 11/5/04 - \$ 4,329 80 US funds. Cancellation Charge for Silver grey tocks and switches and paint. Chassis Engraving Reduction Production Order	Production Order \$49,150.00 \$4,329.80 \$1,200.00 Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500420812 4500420809 4500420809 4500420809 4500423617 4500423617	DST0001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS DST002048DFS DST002048DFS DST002048DFS	00010 000010 000010 000010 00010 00010 00010 00010 00010	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 02/24/2006 12/16/2004 12/16/2004 12/16/2004 12/21/2004 12/21/2004 12/21/2004	25,550,000 25,000,000 33,624,000 26,550,000 3,240,000 3,240,000 1,000 1,000 42,620,000 42,620,000 80,000,000	25,550,000 25,000,000 33,624,000 26,550,000 3,240,000 3,240,000 0,000 0,000 0,000 40,417,000 42,220,000,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2005 02/04/2005 02/25/2005 12/16/2004 12/16/2004 12/16/2004 02/26/2005 02/28/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Roady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$\$500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$\$500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 55,000 16,100 Please remove \$\$500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Roady Tray 7,800 7,800 Cap. PCB Cover 3,500 3,500 Actuator, Selector Switch 350 350 TOTAL \$73,250 \$49,150 Old Chassis Stock as advised 11/5/04 - \$ 4,329 80 US funds. Cancellation Charge for Silver grey tocks and switches and paint. Chassis Engraving Reduction Production Order Production Order	Production Order \$49,150.00 \$4,329.80 \$1,200.00 Production Order Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500420802 4500420809 4500420809 4500420807 4500423617 4500423617 4500423617	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS DST002048DFS DST002049DFS DST002040FS	00010 00030 00040 00060 00060 00010 00010 00010 00020 00030	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/19/2004 12/19/2004 12/19/2004 12/19/2004 12/19/2004 12/19/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004 12/12/2004	25,550,000 25,000,000 33,624,000 26,550,000 3,240,000 3,240,000 1,000 1,000 1,000 42,620,000 42,220,000 41,800,000,000	25,550,000 25,000,000 33,624,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000 42,220,000 40,410,000 40,410,000	01/31/2006 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 02/28/2005 02/28/2005	Production Order	Production Order \$49,150.00 \$4,329.80 \$1,200.00 Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500420802 4500420809 4500420809 4500420807 4500420817 4500423617 4500423617 4500423617	DST0001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS DST002048DFS DST002048DFS DST002048DFS	00010 00030 00040 00060 00060 00010 00010 00010 00020 00030	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/19/2004 12/19/2004 12/19/2004 12/19/2004 12/19/2004 12/19/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004 12/12/2004	25,550,000 25,000,000 33,624,000 26,550,000 3,240,000 3,240,000 1,000 1,000 42,620,000 42,220,000 41,800,000,000 1,1000	25,550,000 25,000,000 33,624,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000 42,220,000 40,410,000 40,410,000	01/31/2006 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 02/28/2005 02/28/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Roady Tray 6,200 7 Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$9500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Poady Tray 7,800 7,800 Cap. PCB Cover 3,500 3,500 Actuator, Selector Switch 350 350 TOTAL \$73,250 \$49,150 Old Chassis Stock as advised 11/5/04 \$ 4,329 80 US funds. Cancellation Charge for Silver grey locks and switches and paint. Chassis Engraving Reduction Production Order Production Order Production Order	Production Order \$49,150.00 \$4,329.80 \$1,200.00 Production Order Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500420802 4500420809 4500420809 4500420807 4500420817 4500423617 4500423617 4500423617	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS DST002048DFS DST002049DFS DST002040FS	00010 00030 00040 00060 00060 00010 00010 00010 00020 00030	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/19/2004 12/19/2004 12/19/2004 12/19/2004 12/19/2004 12/19/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004 12/12/2004	25,550,000 25,000,000 33,624,000 26,550,000 3,240,000 3,240,000 1,000 1,000 1,000 42,620,000 42,220,000 41,800,000,000	25,550,000 25,000,000 33,624,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000 42,220,000 40,410,000 40,410,000	01/31/2006 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 02/28/2005 02/28/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4,500 charge as CPI is responsible for sink marts (did not mention during DFM). Roady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Roady Tray 7,800 7,800 Coap. PCB Cover 3,500 3,500 Actuator, Selector Switch 350 350 TOTAL \$73,250 \$49,150 TOTAL \$73,250 \$49	Production Order \$49,150.00 \$4,329.80 \$1,200.00 Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500420602 4500420602 4500420602 4500420603 4500423617 4500423617 4500423617 4500423617	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS DST002048DFS DST002045DFS DST002051DFS	00020 00030 00040 00050 00066 00010 00010 00010 00010 00010 00010 00020 00040 00050	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004 12/21/2004 12/21/2004	25.550.000 25.000.000 33.624.000 26.550.000 3.240.000 3.240.000 1.000 1.000 42.620.000 41.800.000 41.800.000 42.400.000	25,550,000 25,000,000 25,000,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000 40,417,000 40,410,000 42,220,000 40,410,000 42,400,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 02/28/2005 02/28/2005 02/28/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). FOR Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Abasis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Abasis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Abasis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 500 charge as CPI is responsible for sink marks (did not mention during DFM).	Production Order \$49,150.00 \$4,329.80 \$1,200.00 Production Order Production Order Production Order Production Order Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500420802 4500420809 4500420809 4500420807 4500420817 4500423617 4500423617 4500423617	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS DST002048DFS DST002045DFS DST002051DFS	00020 00030 00040 00050 00066 00010 00010 00010 00010 00010 00010 00020 00040 00050	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/19/2004 12/19/2004 12/19/2004 12/19/2004 12/19/2004 12/19/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004 12/12/2004	25,550,000 25,000,000 33,624,000 26,550,000 3,240,000 3,240,000 1,000 1,000 1,000 42,620,000 42,220,000 41,800,000,000	25,550,000 25,000,000 25,000,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000 40,417,000 40,410,000 42,220,000 40,410,000 42,400,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 02/28/2005 02/28/2005 02/28/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marts (did not mention during DFM). Roady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Roady Tray 7,800 7,800 Coap. PCB Cover 3,500 3,500 Actuator, Selector Switch 350 350 TOTAL \$73,250 \$49,150 Old Chassis Stock as advised 11/5/04 - \$4,329 80 US funds. Old Chassis Engraving Reduction Production Order Chassis part number engraving for Metallic Part # DST002047 for \$ 550.00 US funds. Work completed back on December 1304	Froduction Order Production Order \$49,150.00 \$44,329.80 \$1,200.00 Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500420602 4500420602 450042089 4500420602 4500420617 4500423617 4500423617 4500423617	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS DST002048DFS DST002045DFS DST002051DFS	00020 00030 00040 00050 00066 00010 00010 00010 00010 00010 00010 00020 00040 00050	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004 12/21/2004 12/21/2004	25.550.000 25.000.000 33.624.000 26.550.000 3.240.000 3.240.000 1.000 1.000 42.620.000 41.800.000 41.800.000 42.400.000	25,550,000 25,000,000 25,000,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000 40,417,000 40,410,000 42,220,000 40,410,000 42,400,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 02/28/2005 02/28/2005 02/28/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). FOR Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Abasis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Abasis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Abasis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 500 charge as CPI is responsible for sink marks (did not mention during DFM).	Froduction Order Production Order \$49,150.00 \$44,329.80 \$1,200.00 Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500420602 4500420602 450042089 4500420602 4500420617 4500423617 4500423617 4500423617	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS DST002048DFS DST002045DFS DST002051DFS	00020 00030 00040 00050 00066 00010 00010 00010 00010 00010 00010 00020 00040 00050	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004 12/21/2004 12/21/2004	25.550.000 25.000.000 33.624.000 26.500.000 3.240.000 3.240.000 1.000 1.000 42.620.000 41.800.000 41.800.000 42.400.000	25,550,000 25,000,000 25,000,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000 40,417,000 40,410,000 42,220,000 40,410,000 42,400,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 02/28/2005 02/28/2005 02/28/2005	Production Order Produc	Froduction Order Production Order \$49,150.00 \$44,329.80 \$1,200.00 Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500420602 4500420602 4500420602 4500420603 4500423617 4500423617 4500423617 4500423617	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS DST002048DFS DST002045DFS DST002051DFS	00020 00030 00040 00050 00066 00010 00010 00010 00010 00010 00010 00020 00040 00050	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004 12/12/2004 12/12/2004	25.550.000 25.000.000 33.624.000 26.500.000 3.240.000 3.240.000 1.000 1.000 42.620.000 41.800.000 41.800.000 42.400.000	25,550,000 25,000,000 25,000,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000 40,417,000 40,410,000 42,220,000 40,410,000 42,400,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 02/28/2005 02/28/2005 02/28/2005	Production Order Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marts (did not mention during DFM). PCB Cover 13,200 9,300 Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Roady Tray 7,800 7,800 Cap. PCB Cover 3,500 3,500 Cap. PCB Cover 3,500 3,	Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500420602 4500420602 4500420602 4500420603 4500423617 4500423617 4500423617 4500423617	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS DST002048DFS DST002045DFS DST002051DFS	00020 00030 00040 00050 00066 00010 00010 00010 00010 00010 00010 00020 00040 00050	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004 12/12/2004 12/12/2004	25.550.000 25.000.000 33.624.000 26.500.000 3.240.000 3.240.000 1.000 1.000 42.620.000 41.800.000 41.800.000 42.400.000	25,550,000 25,000,000 25,000,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000 40,417,000 40,410,000 42,220,000 40,410,000 42,400,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 02/28/2005 02/28/2005 02/28/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marts (did not mention during DFM). Roady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$9500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Roady Tray 7,800 7,800 Coap. PCB Cover 3,500 3,500 Actuator, Selector Switch 350 350 TOTAL \$73,250 \$49,150 Old Chassis Stock as advised 11/5/04 - \$4,329 80 US funds. Cancellation Charge for Silver grey tocks and switches and paint. Chassis Engraving Reduction Production Order Production Order Production Order Production Order Chassis part number engraving for Metallic Part # DST002047 for \$ 550.00 US funds. Work completed back on December 13/04 Roady Tray DST001752 - P.O. required for \$ 5,000.00 US - removed \$ 1,200.00 US for 4 ejector pins.	Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500420602 4500420602 4500420602 4500420603 4500423617 4500423617 4500423617 4500423617	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS DST002048DFS DST002045DFS DST002051DFS	00020 00030 00040 00050 00066 00010 00010 00010 00010 00010 00010 00020 00040 00050	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004 12/12/2004 12/12/2004	25.550.000 25.000.000 33.624.000 26.500.000 3.240.000 3.240.000 1.000 1.000 42.620.000 41.800.000 41.800.000 42.400.000	25,550,000 25,000,000 25,000,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000 40,417,000 40,410,000 42,220,000 40,410,000 42,400,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 02/28/2005 02/28/2005 02/28/2005	Production Order Produc	Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500420602 4500420602 4500420602 4500420603 4500423617 4500423617 4500423617 4500423617	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS DST002048DFS DST002045DFS DST002051DFS	00020 00030 00040 00050 00066 00010 00010 00010 00010 00010 00010 00020 00040 00050	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004 12/12/2004 12/12/2004	25.550.000 25.000.000 33.624.000 26.500.000 3.240.000 3.240.000 1.000 1.000 42.620.000 41.800.000 41.800.000 42.400.000	25,550,000 25,000,000 25,000,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000 40,417,000 40,410,000 42,220,000 40,410,000 42,400,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 02/28/2005 02/28/2005 02/28/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Abasis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Abasis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Abasis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis Stock as advised 11/5/04 - \$ 4,329.80 US tunds. Cancellation Charge for Silver grey locks and switches and paint. Chassis Engraving Reduction Production Order P	Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500420602 4500420602 4500420602 4500420603 4500423617 4500423617 4500423617 4500423617	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS DST002048DFS DST002045DFS DST002051DFS	00020 00030 00040 00050 00066 00010 00010 00010 00010 00010 00010 00020 00040 00050	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004 12/12/2004 12/12/2004	25.550.000 25.000.000 33.624.000 26.500.000 3.240.000 3.240.000 1.000 1.000 42.620.000 41.800.000 41.800.000 42.400.000	25,550,000 25,000,000 25,000,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000 40,417,000 40,410,000 42,220,000 40,410,000 42,400,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 02/28/2005 02/28/2005 02/28/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marts (did not mention during DFM). Roady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Roady Tray 7,800 7,800 Cover Roady Tray 8,900 11,900 Cover Roady Tray 7,800 7,800 Cover Roady Tray 8,900 11,900 Cover Roady Tray 8,900 Cover Roady Tray 8,90	Production Order
4500417812 4500417812 4500417812 4500417812 4500417812 4500420602 4500420602 4500420602 4500420603 4500423617 4500423617 4500423617 4500423617	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS DST002048DFS DST002045DFS DST002051DFS	00020 00030 00040 00050 00066 00010 00010 00010 00010 00010 00010 00020 00040 00050	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004 12/12/2004 12/12/2004	25.550.000 25.000.000 33.624.000 26.500.000 3.240.000 3.240.000 1.000 1.000 42.620.000 41.800.000 41.800.000 42.400.000	25,550,000 25,000,000 25,000,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000 40,417,000 40,410,000 42,220,000 40,410,000 42,400,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 02/28/2005 02/28/2005 02/28/2005	Production Order Produc	Production Order
450047812 4500417812 4500417812 4500417812 4500417812 4500420602 4500420602 4500420602 4500420603 4500420617 4500423617 4500423617 4500423617	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS DST001750DFS TO R0090 CAA R0110 DST002047DFS DST002048DFS DST002048DFS DST002045DFS DST002051DFS	00020 00030 00040 00050 00066 00010 00010 00010 00010 00010 00010 00020 00040 00050	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004 12/12/2004 12/12/2004	25.550.000 25.000.000 33.624.000 26.500.000 3.240.000 3.240.000 1.000 1.000 42.620.000 41.800.000 41.800.000 42.400.000	25,550,000 25,000,000 25,000,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000 40,417,000 40,410,000 42,220,000 40,410,000 42,400,000	01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/04/2006 02/25/2005 02/25/2005 12/16/2004 12/16/2004 12/16/2004 12/16/2004 02/28/2005 02/28/2005 02/28/2005	Production Order CPI quote Approved by CLS Comments Chassis 16,600 12,100 Please remove \$4500 charge as CPI is responsible for sink marks (did not mention during DFM). Roady Tray 6,200 ? Please remove cost of 4 ejector pins cost as this was an action by CPI to improve ejection. PCB Cover 13,200 9,300 Please remove \$3900 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Chassis 25,600 16,100 Please remove \$3500 charge as CPI is responsible for sink marks (did not mention during DFM). Cover Roady Tray 7,800 7,800 Cap. PCB Cover 3,500 3,500 Actuator, Selector Switch 350 350 TOTAL \$73,250 \$49,150 Old Chassis Stock as advised 11/5/04 - \$ 4,329 80 US funds. Cancellation Charge for Silver grey tocks and switches and paint. Chassis Engraving Reduction Production Order Prod	Production Order
450047812 4500417812 4500417812 4500417812 4500417812 4500420602 4500420602 4500420602 4500420603 4500420617 4500423617 4500423617 4500423617	DST001751DFS DST001754DFS DST001855DFS DST001855DFS DST001750DFS TO R0090 CAA R00110 DST002047DFS DST002048DFS DST002048DFS DST002051DFS N0010	00010 00010 00010 00010 00010 00010 00010 00010 00010 00010	23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439 23439	12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/13/2004 12/16/2004 12/16/2004 12/16/2004 12/16/2004 12/12/2004 12/12/2004 12/12/2004	25.550.000 25.000.000 33.624.000 26.500.000 3.240.000 3.240.000 3.240.000 1.000 1.000 42.620.000 42.220.000 42.220.000 42.400.000	25,550,000 25,000,000 33,624,000 26,550,000 3,240,000 3,240,000 0,000 0,000 40,417,000 42,220,000 49,417,000 42,400,000 0,000	01/31/2006 01/31/2005 01/31/2005 01/31/2005 01/31/2005 02/25/2005 02/25/2005 02/25/2005 02/25/2005 02/25/2005 02/25/2005 02/25/2005 02/25/2005 02/25/2005 02/25/2005 02/25/2005 02/25/2005 02/25/2005 02/25/2005 02/25/2005	Production Order Produc	Production Order

(3)

Materials Consumed

					Cost
Reg	PO	Invoice (opt)	Description	Cdn\$	US\$
5E+09	5.5E+09		Network Circuits 2000 - PCBs, Tuner Board	\$1,300.00	
5E+09	5.5E+09		Digi-Key - Parts for prototypes		\$1,283.93
5E+09	5.5E+09		Mouser Electronics - Parts for prototypes		\$114.00
5E+09	5.5E+09		Richardson Electronics - Parts for prototypes (connectors)	\$325.90	İ
	4.5E+09		All American Semi Cond - Prototype parts		\$855.00
	4.5E+09		All American Semi Cond - Prototype parts		\$96.00
	4.5E+09	ł	Amphenol RF Div - Prototype parts		\$525.00
	4.5E+09		Arrow Canada - Prototype parts		\$170.00
İ	4.5E+09		Avnet - Prototype parts		\$12,767.19
	4.5E+09		AVX Corp - Prototype Parts		\$75.40
l	4.5E+09		Custom Plastics - SLA&SLS proto parts		\$5,600.00
	4.5E+09		Custom Plastics - Prototype parts		\$11,700.00
	4.5E+09		Custom Plastics - Prototype parts		\$4,329.80
	4.5E+09		Digi-Key - Prototype parts		\$175.40
1	4.5E+09	ĺ	Digi-Key - Prototype parts		\$663.72
	4.5E+09	İ	Irwin Industrial - Prototype Parts		\$500.00
ĺ	4.5E+09		Irwin Industrial - Prototype Parts		\$515.63
	4.5E+09		Kemet - Prototype parts		\$112.50
	4.5E+09		Kemet - Prototype parts		\$551.00
	4.5E+09		KOA Speer - Prototype parts		\$2.70
	4.5E+09		Maxim Integrated Products		\$201.75
	4.5E+09		Network Circuits - Prototype parts		\$750.00
	4.5E+09		SND Electronics - Prototype parts		\$800.00
	4.5E+09		SND Electronics - Prototype parts		\$134.75
-	4.5E+09		SND Electronics - Prototype parts		\$457.10
	4.5E+09		SND Electronics - Prototype parts		\$85.00
	4.5E+09		Tecate Industries - Prototype parts		\$390.00
	4.5E+09		TTI Incorporated - Prototype parts		\$50.00
1	4.5E+09		Tyco Electronics Canada - Prototype parts		\$153.65
	4.5E+09		Viasystems - Prototype parts		\$5,251.20
	4.5E+09		Custom Plastics - Proto plastic resin		\$13,200.00
	4.5E+09		Custom Plastics - Proto plastic resin		\$16,200.00
		·		\$1,625.90	\$77,710.72

Total \$1,625.90 \$77,710.7

05-44481-rdd Doc 5744-3 Filed 11/22/06 Entered 11/22/06 15:22:02 Exhibit C Pg 7 of 15

Contractor/Consultant Work Done in Canada

				Co	ost
Req	PO	Invoice (opt)	Description	Cdn\$	US\$
5000101115	5500043634		Pamela Paterson - Technical Writing Services	\$0.00	
5000099003	5500042736	İ	Ultratek - Regulatory Testing, EMC Immunity Testing	\$8,150.00	
5000099002	5500042878		Ultratek - Regulatory Testing & Filing, FCC Part 15, Sub B Class B	\$13,412.00	
5000099369	5500042912		Global Advantage International - Safety Testing, UL/CSA	\$11,300.00	
5000099747	5500043281		Thermodyne - Environmental Exposure Testing	\$11,000.00	
5000106396	5500045059		Thermodyne - Environmental Exposure Testing	\$2,750.00	
5000099686	5500043190		Bodycote - Environmental Exposure Testing	\$690.00	
	Cross-charge		Celestica PoD - DV Proto build MVA & eng'g services		\$14,811.56
	5500040383		HCL Technologies - Mechanical design NRE	L	\$24,265.00

Total \$47,302.00 \$39,076.56 3

05-44481-rdd Doc 5744-3 Filed 11/22/06 Entered 11/22/06 15:22:02 Exhibit C Pg 8 of 15

6	

	Taken to the first of the first	
Leased Equipment		
Leased Louibilien		2007 2010 TO 2010 F. T. 2017 F. T. 700 SO FOR GARAGE COLORS FOR A POSSO OBSECTION OF COLORS FOR A COLORS FOR F

			Γ	Cost	t
Req	PO	Invoice (opt)	Description	Cdn\$	US\$
5000098865	5500042692		TRS-REN TELCO - SMIQ Rental (3mths, XM signal gen.)	\$4,450.00	- ""
	<u> </u>		Total	\$4,450.00	\$0.0

Delphi Matchbox Sustaining - PL (M6.4d) - Jan to Mar 2005

=	
ᆂ	m
0	
=	447
=	388
	0.00
20	
M	· •
**	985
_	
-	~=
w	
-	
·	~~
_	
•	
•	
	1000
-	
-	15.0
7	27855
	- 00
-	-
•	- A
ж.	3.60
•	
-	4.50
2577	100
O	
. 25.	10 T
•	1 Table 1
_	
~	
w	3
u	_
-	
æ.	30.00
_	
×33.	
46	
=	
1142	
=	330
_	300
•	SENCE)
-	2 ×
	200
=	3
48.50	
	Section 1
**	360.3
_	14.0
65	Enter in the blue cells ONLY. Start in column B
-	100
77	2
+3//15	34 CO.
	-35
_	
æ	Name of Street
=	727
17.	42
_	- CD
T	420 E
=	100
τŒ	3.3
	200
ш.	944
	March !

152 Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Jan - 2005 Jan - 2005 Jan - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2		-	6		4	u c	œ	
Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May -	Denver	Jan - 2005	Jan - 2005	Feb - 2005	Mar - 2005	Apr - 2005	May - 2005	Total
Jan - 2005 Jan - 2006 Feb - 2006 Mar - 2006 Apr - 2005 May - 2006 To Jan - 2005 Jan - 2006 Feb - 2006 Mar - 2006 Apr - 2005 May - 2005 To Jan - 2006 Jan - 2006 Feb - 2006 Mar - 2006 Apr - 2006 May - 2006 To Jan - 2006 Jan - 2006 Feb - 2006 Mar - 2006 Apr - 2006 May - 2006 To Jan - 2006 Jan - 2006 Feb - 2006 Mar - 2006 Apr - 2006 May - 2006 To Jan - 2006 Jan - 2006 Feb - 2006 Mar - 2006 Apr - 2006 May - 2006 To Jan - 2006 Jan - 2006 Feb - 2006 Mar - 2006 Apr - 2006 May - 2006 To Jan - 2006 Jan - 2006 Feb - 2006 Mar - 2006 Apr - 2006 May - 2006 To Jan - 2006 Jan - 2006 Feb - 2006 Mar - 2006 Apr - 2006 May - 2006 To Jan - 2006 Jan - 2006 Feb - 2006 Mar - 2006 Apr - 2006 May - 2006 To Jan - 2006 Jan - 2006 Feb - 2006 Mar - 2006 Apr - 2006 May - 2006 Apr - 2006 Jan - 2006 Feb - 2006 Mar - 2006 Apr - 2006 May - 2006 Apr - 2006 May - 2006 Apr - 2006 May - 2006 Apr - 2006 May - 2006 Apr - 2006 Apr - 2006 May - 2006 Apr - 2006 May - 2006 Apr	SIL a	1	1	•	•	•	•	•
Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To 270 64.0 6.0 7.0 1.0 85.0 16.0 Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To 36.0 5.0 Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To	II B Hrs	Jan - 2005	Jan - 2005	Feb - 2005	Mar - 2005	Apr - 2005	May - 2005	Total
Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2006 May - 2005 To 276.0 64.0 6.0 2.0 7.0 1.0 2.0 7.0 1.0 88.0 6.0 414.0 40.8 46.8	Se	1 1	Jan - 2005	Feb - 2005	Mar - 2005	Apr - 2005	May - 2005	Total
Jan - 2006 Jan - 2006 Feb - 2005 Mar - 2006 Apr - 2006 May - 2006 To 276.0 64.0 6.0 7.0 1.0 95.0 16.0 88.0 6.0 8.0 414.0 88.0 6.0 - 414.0 88.0 6.0 6.0 - 414.0 88.0 6.0 6.0 - 414.0 88.0 6.0 6.0 - 414.0 88.0 6.0 6.0 6.0 6.0 6.0 6.0 6.0 6.0 6.0 6			•	1	τ		1	4
276.0 64.0 6.0 2.0 7.0 1.0 85.0 16.0 36.0 5.0 36.0 5.0 414.0 88.0 6.0 Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To 38,328.46 8,114.12 643.83 46.8	2		Jan - 2005	Feb - 2005	Mar - 2005	Apr - 2005	May - 2005	Total
2.0 95.0 16.0 36.0 5.0 Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To	I		276.0	64.0	6.0			346.0
7.0 1.0 95.0 16.0 36.0 5.0 Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2006 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2006 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To				2.0				2.0
36.0 5.0 Jan-2005 Jan-2005 Feb-2005 Mar-2005 Apr-2005 May-2005 To Jan-2005 Jan-2005 Feb-2005 Mar-2005 Apr-2005 May-2005 To Jan-2005 Jan-2005 Feb-2005 Mar-2005 Apr-2005 May-2005 To Jan-2005 Jan-2005 Feb-2005 Mar-2005 Apr-2005 May-2005 To 38,328.46 8,114.12 543.63 46,8			7.0	1.0				8.0
36.0 5.0 414.0 88.0 6.0 Jan-2006 Jan-2006 Feb-2006 Mar-2006 Apr-2006 May-2006 To Jan-2006 Jan-2006 Feb-2006 Mar-2006 Apr-2006 May-2006 To Jan-2006 Jan-2006 Feb-2006 Mar-2006 Apr-2006 May-2006 To 38.28.46 8,114.12 643.63 Apr-2005 May-2006 To	•		95.0	16,0		The second secon	(III)	111.0
36.0 5.0 Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To 38,328.46 8,114.12 543.63 Apr - 2005 May - 2005 To								
Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To 38,328.46 8,114.12 643.83 46,8	250		36.0	5.0				41.0
Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To 38,328.46 8,114.12 543.63 46,9	. Hrs	1	414.0	88.0	6.0			508.0
Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To	ate :	- 2005	Jan - 2005	Feb - 2005	Mar - 2005	Apr - 2005	May - 2005	Total
Jan - 2005 Jan - 2005 Feb - 2006 Mar - 2005 Apr - 2005 May - 2006 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To	e E	•	•	•			•	•
Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To 414.0 88.0 6.0 Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To	ove Hrs	Jan - 2005	Jan - 2005	Feb - 2005	Mar - 2005		May - 2005	Total
Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005 To	Œ		Jan - 2005	Feb - 2005	Mar - 2005		May - 2005	Total
Jan - 2005 Jan - 2005 Feb - 2006 Mar - 2005 Apr - 2005 May - 2005 To	Hrs	1 1	+	•	1	1 1	•	
Jan - 2005 Jan - 2005 Feb - 2005 Mar - 2005 Apr - 2005 May - 2005	ours	ŧ	414.0	88.0	6.0	•	•	508.0
38,328.46 8,114.12 543.63	s,		Jan - 2005	Feb - 2005	Mar - 2005	Apr - 2005	May - 2005	Total
38,328.46 8,114.12 543.63	er s	1 1	1 1	4 4		• •	1 1	1 1
38,328.46 8,114.12 543.63	ស្	•	ŧ	1	•	·	•	•
	Cost		38,328.46	8,114.12	543.63			46,986.20

05-4	44481-rc	bb	Doc 5	5744-3	3 File	ed 11/2 Pg	22/06 10 of	Ente	ered	11/22/0	06 15:2	22:02	EXA	bit) b)
Rates			75.05	72.73	86.58	66.63 69.74	77.81		33. 10 74. 78						6:06 PM
Total 175.0	Total 39.0	Total	Total	516.0 643.0	0.928	165.0 - 5,931.0	Total	72.0		72.0	Total	Total	6,217.0	485,429.36	07/06/2006 6:
9 - 2005	- 2005	1 - 2005	- 2005				- 2005 - ١				1 - 2005	2005 - r	•	•	Print Date:

Tota 175	Total 39	Total	3,778 516 643 829	165 - 5,931	Total	72	72	Total	Total	6,217
9 Jan - 2005	Jan - 2005	Jan - 2005	Jan - 2005	•	Jan - 2005			Jan - 2005	Jan - 2005	•
8 Dec - 2004	Dec - 2004	Dec - 2004	Dec - 2004 347.0 44.0 5.0 153.0	3.0	Dec - 2004		•	Dec - 2004	Dec - 2004	43,073.33
7 Nov - 2004	Nov - 2004	Nov - 2004	Nov - 2004 531.0 94.0 99.0 73.0	31.0	Nov - 2004		1	Nov - 2004	Nov - 2004	62,674,25
6 Oct - 2004	Oct - 2004	Oct - 2004	Oct - 2004 667.0 163.0 69.0 192.0	60.0	Oct - 2004		1	Oct - 2004	Oct - 2004	- 87,832.24
5 Sep - 2004	Sep - 2004	Sep - 2004	Sep - 2004 460.0 118.0 124.0 97.0	28.0	Sep - 2004		,	Sep - 2004	Sep - 2004	- - 62,888.12
4 Aug - 2004	Aug - 2004 26.0	Aug - 2004	Aug - 2004 437.0 42.0 99.0 147.0	22.0	Aug - 2004	10.0	10.0	Aug - 2004	Aug - 2004	783.0
3 Jul - 2004 23.0	Jul - 2004 13.0	Jul - 2004	Jul - 2004 674.0 28.0 130.0 147.0	5.0	Jul - 2004	62.0	62.0	Jul - 2004	Jul - 2004	1,082.0 84,560.70
2 Jun - 2004 92.0	Jun - 2004 -	Jun - 2004	Jun - 2004 496.0 27.0 115.0 20.0	16.0	Jun - 2004			Jun - 2004	Jun - 2004	766.0 62,536.81
1 May - 2004 60.0	May - 2004	May - 2004	May - 2004 166:0 2:0	168.0	May - 2004			May - 2004	May - 2004	228.0 20,257,22
Denver Total Site Hrs	Salem Total Site Hrs	San Jose Total Site Hrs	Electrical Mechanical PCD Program Mgt	Software Tech Validation Total Site Hrs	Vimercate	Electrical Mechanical PCD Program Mgt Quality Software	Tech Validation Total Site Hrs	<u>Kidsgrove</u> Total Site Hrs	China Total Site Hrs	Total CLS Hours Total Burden Cost

Enter in the blue cells ONLY. Start in column B

Delphi Matchbox - PL (M5.4a) - May to Dec 2004

Celestica Confidential

05-44481-rdd Doc 5744-3 Filed 11/22/06 Entered 11/22/06 15:22:02 Exhibit © Pg 11 of 15



Leslie Smeyers/Inc/Celestica 07/04/2006 01:46 PM To John DaCosta/Inc/Celestica@Celestica

cc Glenn Goertzen/Inc/Celestica@Celestica, Steven DeCamillis/Inc/Celestica@Celestica

bcc

Subject Re: Delphi - Payment received

Here is the full detail of the Delphi invoices currently sitting in 6100.

				A : :	AR	Payment	Danis and S	Copy of	Copy of	C
Invoice #	PO#	# Inv Date	Due Date	e Original AR	Amount	Made	Payment S	PO	Inv	
90769317	S3S32298	09/23/2005	10/23/2005	\$ 6,274.02	\$ 6,274.02	N	\$ -	Υ	Υ	Si
90769318	S3S0339	09/23/2005	10/23/2005	\$ 31,896.00	\$31,896.00	N	\$ -	N	Υ	Dale War
				\$171,793.50	\$20,211.00	Υ	\$151,582.50	N	Υ	Frank Gr

¹Note - Invoice 90557578 was for 2550 pcs (17 skids), shipment number 50117914. Delphi only released payment for 2250 pcs o short-paid (2 skids) - packing slip and carrier manifest corresponding to this shipment was provided clearly showing 17 skids was or received by the Delphi's Hub has been provided.

John DaCosta



To: Leslie Smeyers/Inc/Celestica@Celestica

cc: Glenn Goertzen/Inc/Celestica@Celestica, Steven

DeCamillis/Inc/Celestica@Celestica

Subject: Re: Delphi - Payment received

Can you confirm the details of these invoices (dates, PO's, etc). Also, please indicate if any part of the invoice has been offset with a payment or credit which would make the outstanding amount different then the face amount of the invoice.

Thanks. Leslie Smeyers/Inc/Celestica



Leslie Smeyers/Inc/Celestica 05/04/2006 05:40 PM

To Glenn Goertzen/Inc/Celestica@Celestica, Steven DeCamillis/Inc/Celestica@Celestica cc John DaCosta/Inc/Celestica@Celestica

Subject Delphi - Payment received

Payment received for invoice 90802793 - \$10,100.28. Total AR owed by Delphi is \$58,381.02

05-44481-rdd Doc 5744-3 Filed 11/22/06 Entered 11/22/06 15:22:02 Exhibit C Pg 12 of 15

M CELESTICA.

INVOICE

Invoice No: 90769317

Print Date : 06-Jul-06 Invoice Date : 23-Sep-05

Celestica Corporation -CNAR 9 Northeastern Blvd. SALEM, New Hampshire 03079, USA

(REPRINT)

Bill To:

Delphi Saginaw Plant 3 Procurement Lab 3900 East Holland Road SAGINAW MI 48601 USA Ship To:

Delphi Saginaw Plant 3 Procurement Lab 3900 East Holland Road SAGINAW MI 48601 USA

Payer Account Number: 3000005637
Payment Terms: 30 Days from Invoice Date

Reference Info:

Customer PO: S3S32298

CLS Line No.	Cust PO Item	Part Number Description	Qty Invoiced	Unit Price	MOU	Extended Price
10	1	Z-SERVICE NRE TOOLING Shipment No.:	1	1,714.95	EA	1,714.95
20	3	Z-SERVICE SX085893 POPULATED ASSY Shipment No.:	2	1,206.40	EA	2,412.80
30	5	Z-SERVICE NRE FOR SX085893	1	2,146.27	EA	2,146.27
		Shipment No.:	•	6,274.02 USD		

WE HEREBY CERTIFY THAT THIS INVOICE IS TRUE AND CORRECT TO THE BEST OF OUR ABILITY AND THAT IT CONTAINS A TRUE STATEMENT OF THE COST OF THE GOODS **Send Payment To:**

Celestica Inc 12578 Collections Center Drive Chicago, Illinois 60693 U.S.A 05-44481-rdd Doc 5744-3 Filed 11/22/06 Entered 11/22/06 15:22:02 Exhibit C Pg 13 of 15

Celestica Corporation -CNAR 9 Northeastern Blvd.

INVOICE

(REPRINT)

Invoice No: 90769318

Print Date : 06-Jul-06 Invoice Date : 23-Sep-05

Bill To:

SALEM, New Hampshire 03079, USA

> Delphi Product and Service Solution 1441 West Long Lake TROY MI 48098 USA

Ship To:

Delphi Product and Service Solution c/o Cat Logistics 6032 Gateway Drive PLAINFIELD IN 46168 USA

Payer Account Number: 3000005595
Payment Terms: 30 Days from Invoice Date

Reference Info:

Customer PO: S3S0339

CLS Line No.	Cust PO Item	Part Number Description	Qty Invoiced	Unit Price	UOM	Extended Price
10		Z-SERVICE	. 1	31,896.00	ΕA	31,896.00
		PCD design service				
		Shipment No.:				
		PCD design service for under t	oody controller board			
			•	Total Debit Amo	unt	31,896.00
			Currency		тсу	USD

WE HEREBY CERTIFY THAT THIS INVOICE IS TRUE AND CORRECT TO THE BEST OF OUR ABILITY AND THAT IT CONTAINS A TRUE STATEMENT OF THE COST OF THE GOODS

Send Payment To:

Celestica Inc 12578 Collections Center Drive Chicago, Illinois 60693 U.S.A Pg 14 of 15

BILLING INVOICE

(REPRINT)

Billing Invoice No: 90557578

Print Date : 06-Jul-06 Invoice Date : 08-Feb-05

Bill To:

9 Northeastern Blvd. SALEM, New Hampshire 03079, USA

> **DELPHI PRODUCT & SERVICES SOLUTIONS** 1441 WEST LONG LAKE ROAD TROY MI 48098 USA

Ship To:

DELPHI PRODUCT AND SERVICE SOLUTION C/O CAT LOGISTICS 6032 GATEWAY DRIVE PLAINFIELD IN 46168 USA

Payer Account Number: 3000004569 Payment Terms: 30 Days from Invoice Date

Reference Info:

Customer PO: 550060383

Carrier Name: Verspeeten Cartage Inc INCOTERMS: EXW (Port Hope)

Waybill No.: 228762

Delivery Note/Line No.: 80841263 / 000010

Broker

PER FEDERAL EXPRESS

Extended Part Description: FM Radio, XM Antenna

CLS Line No.	Cust PO Item	Part Number Description	Qty Invoiced	Unit Price	MOU	Extended Price
10		DST002042	2.550	67.37	EA	171,793.50
10			,	07.57	LA	17 1,7 00.00
		Roady2 Personal Audio System Top-L	ever A			
		Customer Specific PN Ref: SA10109-	11P1			
		Country of Origin: Ontario, Canada				
		Shipment No.: 228762				
				Total Invoice Val	lue	171,793.50
				Currency		USD

TOTAL SHIPMENT DETAILS - SHIPMENT No. 228762

TOTAL OTHER METT DE TALES OTHER METT TO LEST OF										
Handling Unit Details		Wei	ght							
Unit Reference#	Length	Width	Height	Net Weight	Gross Weight					
1003721875	48	40	46 "	431.000	431.000					
1003721876	48	40	46 "	431.000	431.000					
1003721877	48	40	46 "	431.000	431.000					
1003721878	48	40	46 "	431.000	431.000					
1003721879	48	40	46 "	431.000	431.000					
1003721880	48	40	46 "	431.000	431.000					
1003721881	48	40	46 "	431.000	431.000					
1003721882	48	40	46 "	431.000	431.000					
1003721883	48	40	46 "	431.000	431.000					
1003721884	48	40	46 "	431.000	431.000					
1003721885	48	40	46 "	431.000	431.000					
1003721886	48	40	46 "	431.000	431.000					
1003721887	48	40	46 "	431.000	431.000					
1003721888	48	40	46 "	431.000	431.000					

05-44481-rdd Doc 5744-3 Filed 11/22/06 Entered 11/22/06 15:22:02 Exhibit C Pg 15 of 15

M CELESTICA.

BILLING INVOICE

Billing Invoice No: 90557578

Print Date : 06-Jul-06 Invoice Date : 08-Feb-05

Celestica Corporation -CNAR 9 Northeastern Blvd. SALEM, New Hampshire 03079, USA

(REPRINT)

431,000 431,000

Total # of Units	17		Tota	l Weight	7,327.000	7,327.000
1003721891		48	40	46 "		
1003721890				40 4	431,000	431.000
4000704000		48	40	46 *	431.000	431.000
1003721889		40			404.000	431.000
		48	40	46 "	431.000	431.000

WE HEREBY CERTIFY THAT THIS INVOICE IS TRUE AND CORRECT TO THE BEST OF OUR ABILITY AND THAT IT CONTAINS A TRUE STATEMENT OF THE COST OF THE GOODS

Send Payment To:

Celestica Inc 12578 Collections Center Drive Chicago, Illinois 60693 U.S.A